



New Britain Township

207 Park Avenue
Chalfont, PA 18914
Phone: (215) 822-1391
Fax: (215) 822-6051
nbt@newbritaintownship.org

Inspection Report

2019-10261-U01

Summary

Property: 160 NEW GALENA ROAD
Permit Number: 2019-10261-U01
Type: Final U & O
Inspector: Bob Skelton
Inspection Date:
Inspection Time:
Description of Work: RESIDENTIAL

Parcel Number: 26-001-059
Status: Complete
Scheduled By: JoAnn Lapp
Call Date: 08/28/2019
Call Time: 10:00 AM

Results

Results: NEED SMOKE DETECTOR IN BEDROOM HALLWAY & IN ALL BEDROOMS; NEED CARBON MONOXIDE DETECTOR ON FIRST FLOOR & BEDROM HALL UPSTAIRS (CAN BE COMBOS); NEED 36" GUARDS ON 2 SIDES OF PATIO, NO MORE THAN 4" GAP; NEED 4" ADDRESS NUMBERS ON BOTH SIDES OF MAILBOX; NEED HANDRAIL ON RIGHT TO UPPER 2 BEDROOMS, MUST BE FULL LENGTH.

Construction Information

Sq Ft:
Estimated Value: \$0.00

Type: Use & Occupancy
Category:

Contacts

Contact Type: Permit Holder
Company Name:
Full Name:
Address:
Email:

Home Phone:
Business Phone:

Contact Type: Applicant
Company Name:

Full Name: THOMAS & MARY DAVIS
Address: 160 NEW GALENA ROAD, LINE LEXINGTON, PA 18932
Email:

Home Phone:
Business Phone:



Building Inspector Signature

28 Aug 2019
Date