

# TRUCK # 39

Year: 1979  
Make: MACK HYDROSEEDER  
Model #:  
Vin #: R686ST28628  
Weight: 50000  
Fuel: DIESEL  
License #: 68711KA  
Date of Purchase: 7/1/2010

<u>Part #'s:</u>	<u>Part Type:</u>	<u>Part #:</u>
TRUCK	Fuel Filter	33216 & 33219
	Oil Filter	( 3 ) - 51791
	Coolant Filter	24429
	Engine Oil	52 QT - 15W40
	Rear Axle Seal	370022A
	Rear Brake Shoes	C4311E
	HYDROSEEDER	John Deere Engine
Fuel Filter		33370
Air Filter		42222
Oil Filter		51243
Engine Oil		6 QT - 15W40
Fuel Cap		10623 (STANT)
Starter		SE501400 (Five Star Equip)
Battery		4- Deka 904MF 1200 norm 32 deg. 1000 CCA
Belt		3189
Valve		7385
Radiator		AT48171 \$500.00

# TRUCK # 39

DATE	MILES	WORK COMPLETED	MISC
8/3/10	89,939	Serviced engine - Oil, Lube, Grease, & Filters. - Checked all lights - Changed right front rear axle seal - Checked brake adjusters. HYDROSEEDER REPAIRS- Serviced engine (oil, lube filters, grease) - Installed stand pipe for filling with water - installed spray boom on rear of truck - Built fill hoses - Ran & tested tank & pump.	195 hrs.
10/3/10	90,055	Cleaned battery box & welded on cover - changed bushing in front left spring - cleaned rear end breather's - washed oil off right front rear tire - checked clutch adj. on sprayer - checked antifreeze, it is "ok" - <b>"NEEDS OIL SEAL CHANGED" ON RIGHT FRONT REAR</b>	204 hrs
8/12/11	90,519	NYS Inspection- replaced rear right front wheel seal - Installed a guard on seeder muffler - Installed a fence on top of tank - Replaced exhaust pipe & flex pipe.	
3/28/12	90,730	Air up tires - Grease - Charge batteries - Check brake adjustment Check lights - Rear slacks need attention.	245 hrs.
9/6/12	91,318	NYS Inspection - Replace chain coupler on right auger - Needs main chain coupler soon.	
10/1/12		Replace main chain coupler	
4/15/13	91,546	Replace fuel lines on rear motor - Check over - WILL NEED LEFT REAR WHEEL SEAL.	
5/8/13	0	Hydroseeder - Install starter & checkover.	
5/31/13	92,139	Serviced - Truck & engine on back - Install new seal & brakes on left rear axle - Weld hose guard on back by muffler - Put new flashing light on back - Check fluid levels - Grease - Adjust brakes.	317 hrs.
9/20/13	92,268	NYS Inspection - Replaced 3 rear axle brake shoes & seals - Check over.	
10/7/13	92,276	Add 2 maxi air chambers to the rear axle.	
5/13/14	92,369	Install battery cutoff - Check all brakes - Rebuild safety cage for tank - Replace all for batteries - Grease & check over.	
7/31/14		Work on radiator for hydroseeder - 3 out of 4 mounts broke off of radiator hole in tank - Resoulder mounts & fix hole in tank - Should get new radiator if we are going to keep it.	
9/8/14	92,743	Wash off trans & adjust clutch - Tighten alt belts - Add antifreeze to back radiator.	
9/26/14	92,785	NYS Inspection - lube - check over.	
5/7/15	92,820	Check all fluid's. Check brake adjustment. Change left front tire. Service engine. On back, put new oak board's under tank. Weld up valve on back. Fix hand railing on top. Check air pressure in tires. Put new brake hose's on front. Grease. Put used 3 way valve on pump system. Weld up both fender's.	366 hrs
5/27/15	92,883	Put new seals in tower gun, rebuilt throttle for rear engine, took valve apart to clean & grease.	
8/22/15		Change starter solenoid on john deere engine, build screen for inside tank, put new valve on for top gun, fix throttle on power unit, new belt grease	
10/16/15	93,245	NYS inspection, check brake adjustment	
5/25/16	93,395	Service engine and fuel filters and coolant filter; adjust brakes adjust clutch, grease, check all fluid levels	431
6/16/16	93,452	work on radiator on power unit and wash	